


Coleman Mach 8 w/o Pressure Switch

Legend:
 S = Start
 C = Common
 H = Hermatic
 R = Run
 OL = Overload Switch
 (Disconnected)
 (Dotted line)

CAUTION!
SHOCK HAZARD!
 Disconnect power supply before servicing any electrical component.



Coleman Mach 8 w/ Pressure Switch

Legend:
 S = Start
 C = Common
 H = Hermatic
 R = Run
 OL = Overload Switch
 (Disconnected)
 (Dotted line)

CAUTION!
SHOCK HAZARD!
 Disconnect power supply before servicing any electrical component.

